




Version FP1A

Measured: 18/04/2019

1 Dundas Street West Toronto, Ontario, Canada Floor 02

Please refer to corresponding BOMA Office 1980 Area Chart: 1dundas-b80-6a.pdf



This work product has been prepared by Extreme Measures Inc. pursuant to a contract with the Client for the sole benefit of and use by the Client. No third party may rely on this work product without the receipt of a reliance letter from Extreme Measures Inc.





